## DADA LAKHMI CHAND STATE UNIVERSITY OF PERFORMING AND VISUAL ARTS, SECTOR-6, ROHTAK NOTICE INVITING QUOTATIONS

Sealed percentage/item rate quotations are hereby invited for and on behalf of the work from noted below DLCSUVPA, Rohtak for Registrar suppliers/Agencies/Contractors of Haryana PWD B&R, Public Health, Central PWD, H.U.D.A & Municipal corporation on plain paper on dated 10.06.2025 at 3:00 PM. Quotations will be opened at the same date and same time in the presence of quotationers or their representative who may like to be present at that time. All rate should be quoted including GST.

Description	App-Amt.	Time Limit
Repairing of Air-conditioner of various departments and Guest House, DLCSUPVA, Rohtak.  (Details of scope of work attached with the notice)		10 Days

NO. DLCSUPVA/UEW/ E \04-08

Copy of the above is forwarded to the following for information and necessary action:-

- 1. Accounts Officer/ Nominee
- 2. SDE (Electrical)
- 3. Supdtt. (UEW)
- 4. JE (E)
- 5. IT Cell to upload on website please.

DNIQ for repairing of Air-conditioner of various departments and Guest House, DLCSUPVA, Rohtak. Approx. Amount = Rs. 98,176/-						
Sr. No.	Description	Qty.	Unit	RATE with taxes to be Quoted by Contractor / Supplier	Amount	
1.	Replacement of PCB (Indoor unit) of 1.5 Ton AC of Hajer make.	01	No.			
2.	Replacement of outdoor fan motor of non-inverter 1.5-ton AC of Daikin make. Rating 220-240V, 50 Hz, 0.5 A, 60 watt	01	No.			
3.	Replacement of compressor of non-inverter 1.5- ton AC of Hitachi make	01	No.			
4.	Pressure leak arresting and gas refilling of 4-ton Tower AC of Panasonic make	02	No.			
5.	Pressure leak arresting, gas refilling and replacing of capacitor of 2 Ton Hitachi make AC.	01	No.			
6.	Pressure leak arresting and gas refilling of 1.5 Ton Voltas make AC.	01	No.	-		
7.	Replacement of capacitor 50 ± 5 MFD of 1.5 Ton AC of Hitachi make	01	No.			
8.	Replacement of condenser coil, capacitor 50 ± 5 MFD and gas refilling of 1.5 Ton AC of Hitachi make	01	No.			
9.	Pressure leak arresting and gas refilling of 4-ton Tower AC of Panasonic make	02	Nos.			
10.	Replacement of Indoor unit PCB of 1.5 Ton Hitachi make AC	01	No.			
11.	Repairing and gas refilling of Samsung make double door refrigerator	01	No.			

## Time Limit: 10 Days

## Note: -

- 1. The work should be executed strictly as per the specification mentioned in DNIQ.
- 2. Agency must quote the rates inclusive of GST.
- 3. Delay Penalty will be as per UAC.